

Keramická tělíska

Popis

Hlavní použití keramických tělísek: odstraňování otřepů, zaoblení ostrých hran, odstraňování šupin, vyhlazení a homogenizace povrchu, leštění. Doporučeno pro ocel (uhlík, nerez, speciální typy). Je možné vyrobit speciální typy čipů pro potřeby konkrétních uživatelů.

TYP TYPE	TVAR SHAPE	TROJ- ÚHLENÍK TRIANGLE	TROJ- ŠIKMÝ ŘEZ ANGLE CUT	VÁLEC CYLINDER	VÁLEC ŠIKMÝ ŘEZ ANGLE CUT CYLINDER	HVĚZDA 4 STAR	HVĚZDA 3 TRISTAR	HVĚZDA 4 ŠIKMÝ ŘEZ ANGLE CUT TRISTAR	VÁLEC DOUBLE ANGLE CUT CYLINDER	ELIPSA ŠIKMÝ ŘEZ ANGLE CUT ELLIPSE	ELIPSA ŠIKMÝ ŘEZ ANGLE CUT ELIPSE	HROT ARROW HEAD	KULÍČKA BALL	KUŽEL CONE	PYRAMIDA PYRAMID
BROUŠENÍ GRINDING	AA	10x10;15x15; 20x20	10x10 15x15 20x20												
LEŠTĚNÍ POLISHING	A	3x3; 4x4; 5x5; 6x6; 8x8; 10x10; 8x8; 10x10; 12x12; 15x15; 20x20; 25x25; 30x30	6x6; 8x8; 10x10; 12x12; 15x15; 20x20; 25x25; 30x30	4x10; 6x12; 8x10; 10x20; 15x20	6x12, 8x10; 10x20; 15x20	10x10; 20x10; 30x15; 30x30; 45x15	15x7; 15x15; 30x15; 30x25	15x7; 15x15; 30x15; 30x25	10, 12, 15, 18, 15	10x5x10; 15x7x15; 25x10x25	10x5x10; 15x7x15; 25x10x25	10x10; 15x10; 20x12		15x15; 30x30	38x38
B	3x3; 4x4; 5x5; 6x6; 8x8; 10x10; 12x12; 15x15; 20x20; 25x25; 30x30; 35x35; 40x40	6x6; 8x8; 10x10; 12x12; 15x15; 20x20; 25x25; 30x30	4x10; 6x12; 8x10; 10x20; 15x20	3x15; 4x12; 6x12, 8x10; 10x20; 15x20	10x10; 20x10; 30x15; 30x30; 45x15	15x7; 15x15; 30x15; 30x25	15x7; 15x15; 30x15; 30x25	10, 12, 15, 18, 15	10x5x10; 10x5x12; 15x7x15; 25x10x25	10x5x10; 10x5x12; 15x7x15; 25x10x25	10x10; 15x10; 20x12	6; 8; 10	15x15; 30x30	38x38	
BD	12x12; 15x15; 20x20; 25x25; 30x30; 40x40	12x12; 15x15; 20x20; 25x25; 30x30	8x10; 10x20;	8x10; 10x20; 15x20	10x10; 20x10; 20x20; 45x15	15x7; 15x15; 30x15	15x7; 15x15; 30x15	10, 12, 15, 18, 15	10x5x10; 15x7x15; 25x10x25	10x5x10; 15x7x15; 25x10x25	10x10; 15x10; 20x12				
BC	8x8; 10x10; 15x15; 20x20	8x8; 10x10; 15x15; 20x20	4x10; 6x12; 8x10; 10x20; 15x20	6x12, 8x10; 10x20	10x10; 20x10; 20x20	15x7; 15x15	15x7; 15x15	10, 12, 15, 18, 15	10x5x10; 15x7x15; 25x10x25	10x5x10; 15x7x15; 25x10x25	10x10; 15x10; 20x12	4; 6; 8	15x15		
C	3x3; 4x4; 6x6; 10x10; 12x12; 15x15;	6x6		3x15; 4x12; 6x12, 8x10		15x7	15x7	10, 12, 15, 18, 15	10x5x10	10x5x10			6; 8		
G	3x3; 4x4; 5x5; 6x6; 8x8; 10x10; 12x12; 15x15	6x6; 8x8; 10x10; 12x12; 15x15	4x10; 6x12; 8x10;	3x6; 4x6; 4x12; 6x12, 8x10; 10x8	10x10; 20x10	15x7; 15x15; 30x15; 30x25	15x7; 15x15; 30x15; 30x25	10, 12, 15, 18, 15	10x5x10; 15x7x15; 25x10x25	10x5x10; 15x7x15; 25x10x25	10x10; 15x10; 20x12	4; 6; 8; 10			
P	4x4; 6x6	4x4; 6x6	3x10; 4x6; 4x10; 6x10;	3x6; 3x10; 4x6; 4x10; 5x10; 6x12; 8x10; 10x10; 12x12		10x10; 15x7	10x10; 15x7		10x5x10; 15x5x15	10x5x10; 15x5x15		3; 4; 5; 6; 8			

ÚČINNOST / ABRASIVE EFFICIENCY:



hrubé čištění (strong grinding / rough procesing)



vyhlažování, leštění/konečná úprava (smoothing, polishing / finishing)

Ceramic Chips

Description

Main application of ceramic chips: deburring, rounding of sharp edges, scale removal, smoothing and surface homogenization, polishing. Recommended for steel (carbon, stainless, special types). We manufacture special types of chips for specific users' demand.